

Analyte	Screening Level (mg/kg) Hikers and Campers
Aluminum	3,300,000
Antimony	3,000
Arsenic	4200*
Barium	670,000
Beryllium	6700
Cadmium	1700
Chromium	4,300,000
Cobalt	1000
Copper	130000
Iron	2,300,000
Lead	20,000*
Manganese	160,000
Mercury	1000
Nickel	67,000
Silver	17,000
Thallium	33
Vanadium	830
Zinc	50,000

